

Onderhoudshistorie — L111NX

19 registraties

Omschrijving	Km-stand	Garage	Datum
OHV Intern BU	0	ANWB BV	18/02/2022
225/60 R18 104W - Links Voor	31.610	HEDIN AUTOMOTIVE 3F R'DAM N	18/10/2022
225/60 R18 104W - Rechts Voor	31.610	HEDIN AUTOMOTIVE 3F R'DAM N	18/10/2022
Onh 30.000 Km	31.610	HEDIN AUTOMOTIVE 3F R'DAM N	18/10/2022
Ruitenwiss.blad V - Midden	31.610	HEDIN AUTOMOTIVE 3F R'DAM N	18/10/2022
Carrosserie Batterij	42.150	HEDIN AUTOMOTIVE 3F R'DAM N	27/02/2023
Onh 60.000 Km	54.429	HEDIN AUTOMOTIVE 3F R'DAM N	25/09/2023
Remmen Remvloeistof	54.429	HEDIN AUTOMOTIVE 3F R'DAM N	25/09/2023
225/60 R18 100V - Links Achter	67.203	HEDIN AUTOMOTIVE 3F R'DAM N	05/04/2024
225/60 R18 100V - Links Voor	67.203	HEDIN AUTOMOTIVE 3F R'DAM N	05/04/2024
225/60 R18 100V - Rechts Achter	67.203	HEDIN AUTOMOTIVE 3F R'DAM N	05/04/2024
225/60 R18 100V - Rechts Voor	67.203	HEDIN AUTOMOTIVE 3F R'DAM N	05/04/2024
Interieur Hoedenplank	67.203	HEDIN AUTOMOTIVE 3F R'DAM N	05/04/2024
Onh 90.000 Km	74.411	HEDIN AUTOMOTIVE 3F R'DAM N	05/07/2024
APK icm beurt	97.063	HEDIN AUTOMOTIVE 3F R'DAM N	16/06/2025
Onh 100.000 Km	97.063	HEDIN AUTOMOTIVE 3F R'DAM N	16/06/2025
Bandreparatie	102.330	HEDIN AUTOMOTIVE 3F R'DAM N	29/09/2025
Electr. algemeeAccu	116.192	ANWB BV	10/05/2026
Stranding BI	116.192	ANWB BV	10/05/2026